

The listed chassis numbers are known to have been manufactured within the specified date range (01 May 2015 and 30 June 2016). However, if you have a chassis that has been manufactured by G&S Chassis that has a Control Rider TS Suspension System, or you are unsure if your chassis is affected by this recall, please contact us immediately so that we can advise you.

CHASSIS NUMBER	CHASSIS NUMBER	CHASSIS NUMBER	CHASSIS NUMBER	CHASSIS NUMBER	CHASSIS NUMBER	CHASSIS NUMBER	CHASSIS NUMBER	CHASSIS NUMBER	CHASSIS NUMBER
BC15126	DC4901	DC5151	E6926	G144549	KC1597	KW4638	LC3293	LC3489	ORV16020
BL00100	DC4912	DC5161	EC15091	G144552	KW4368	KW4645	LC3293	LC3511	ORV16023
BL00101	DC4917	DC5163	EC15832	G144553	KW4397	KW4647	LC3294	LSA16511	ORV16028
BL00102	DC4924	DC5170	EC20738	G144554	KW4435	KW4649	LC3301	MO15079	ORV16029
BL00103	DC4925	DC5171	EC20754	G144555	KW4460	KW4654	LC3308	NC2804	ORV16033
BL00104	DC4926	DC5179	EC20967	G144556	KW4461	LC2870	LC3313	NC2815	ORV16034
BL00105	DC4944	DC5183	EMC15008	G144551	KW4475	LC2874	LC3313	NC2850	ORV16038
BL00106	DC4950	DC5185	EMC16003	GG15250	KW4496	LC2957	LC3317	NC2860	ORV16040
BL00107	DC4953	DC5186	EMC16007	GG15283	KW4503	LC2964	LC3318	NC2931	ORV16042
BL00108	DC4981	DC5200	ESS0024	GN6305	KW4542	LC3046	LC3321	NC2932	ORV16043
BL00109	DC5001	DC5205	ESS0096	H2376	KW4547	LC3079	LC3322	NC3040	ORV16044
BL00110	DC5031	DC5213	FCC15016	H2377	KW4557	LC3092	LC3332	NC3049	ORV16049
BL00111	DC5048	DC5215	FCC15018	H2379	KW4559	LC3098	LC3344	NC3061	ORV16054
BL00112	DC5053	DC5222	FCC15021	HL15042	KW4560	LC3131	LC3348	NC3099	ORV16055
BL00115	DC5064	DC5254	G14450	HL15042A	KW4567	LC3135	LC3354	NC3118	ORV16059
BM1524	DC5067	DC5302	G144507	IAN	KW4573	LC3167	LC3355	NC3127	ORV16062
BM1605	DC5074	DC5369	G14451	J&D001	KW4576	LC3198	LC3357	NC3169	ORV16065
BM1617	DC5086	DM222	G144512	JID1968	KW4590	LC3223	LC3365	NC3200	ORV16074
BM1618	DC5097	DM230	G144515	KC15105	KW4603	LC3224	LC3366	NC3211	ORV16058
BM1620	DC5114	DM232	G144519	KC1543A	KW4607	LC3225	LC3370	NC3238	OTM15066
BM1621	DC5123	DM245	G144522	KC1543B	KW4615	LC3233	LC3375	NC3305	OTM15066
BSCP0291	DC5124	E6821	G144529	KC1548B	KW4616	LC3234	LC3383	NC3307	OTM15078
BSCQ1577	DC5134	E6830	G144534	KC1555	KW4623	LC3235	LC3388	ORV15062	OTM16013
BSCQ1595	DC5141	E6848	G144536	KC1566	KW4625	LC3236	LC3389	ORV15076	RC144558
BSCQ1597	DC5143	E6855	G144540	KC1571	KW4630	LC3238	LC3390	ORV15099	RC2591
C1623	DC5146	E6870	G144541	KC1572	KW4631	LC3246	LC3415	ORV15102	RC2597
CC0019	DC5148	E6879	G144544	KC1591	KW4636	LC3251	LC3428	ORV16002	RC2612
COSY1692	DC5150	E6883	G144546	KC1596	KW4637	LC3265	LC3428	ORV16010	RC2622

The listed chassis numbers are known to have been manufactured within the specified date range (01 May 2015 and 30 June 2016). However, if you have a chassis that has been manufactured by G&S Chassis that has a Control Rider TS Suspension System, or you are unsure if your chassis is affected by this recall, please contact us immediately so that we can advise you.

CHASSIS NUMBER	CHASSIS NUMBER	CHASSIS NUMBER	CHASSIS NUMBER	CHASSIS NUMBER	CHASSIS NUMBER	CHASSIS NUMBER	CHASSIS NUMBER	CHASSIS NUMBER
RC2640	RC2790	RC2906	RC2980	RC3067	RC3177	TC16044	VC1586	VC16133
RC2643	RC2792	RC2907	RC2981	RC3068	RVC5264	TC16048	VC1587	VC16134
RC2652	RC2803	RC2908	RC2986	RC3079	SC16258	TC16051	VC1591	VC16135
RC2664	RC2810	RC2910	RC2988	RC3089	SL1554	TC16056	VC1592	VC16136
RC2667	RC2813	RC2914	RC2998	RC3093	SL1556	TC16059	VC1593	VC16137
RC2672	RC2816	RC2919	RC3005	RC3099	ST1575	TC16062	VC1594	VC16138
RC2674	RC2817	RC2920	RC3008	RC3100	ST1577	TC16067	VC1597	VC16139
RC2675	RC2822	RC2923	RC3011	RC3101	ST1620	TC16069	VC1598	
RC2681	RC2832	RC2933	RC3015	RC3105	ST1625	TC16078	VC1599	
RC2686	RC2833	RC2935	RC3017	RC3107	ST1629	TC16104	VC16112	
RC2707	RC2838	RC2943	RC3018	RC3108	ST1632	TC16125	VC16113	
RC2713	RC2839	RC2944	RC3019	RC3110	ST1638	TC16145	VC16116	
RC2715	RC2840	RC2947	RC3023	RC3111	ST1640	TC16153	VC16117	
RC2719	RC2841	RC2949	RC3029	RC3112	TC15078	TLCC1513	VC16118	
RC2721	RC2847	RC2950	RC3034	RC3113	TC15079	TLCC1514	VC16119	
RC2722	RC2853	RC2953	RC3037	RC3114	TC15135	TLCC1515	VC16120	
RC2732	RC2863	RC2956	RC3042	RC31165	TC15135	TLCC1601	VC16121	
RC2740	RC2867	RC2959	RC3043	RC3119	TC15136	TLCC1604	VC16123	
RC2741	RC2871	RC2960	RC3044	RC3135	TC15175	VC15102	VC16124	
RC2745	RC2875	RC2964	RC3050	RC3137	TC15211	VC15103	VC16125	
RC2753	RC2882	RC2968	RC3051	RC3138	TC15226	VC15104	VC16126	
RC2756	RC2889	RC2969	RC3057	RC3141	TC16020	VC15105	VC16127	
RC2771	RC2890	RC2970	RC3058	RC3154	TC16022	VC15106	VC16128	
RC2779	RC2902	RC2972	RC3061	RC3156	TC16037	VC15108	VC16130	
RC2783	RC2904	RC2973	RC3063	RC3158	TC16043	VC15111	VC16132	